01272.007910.4 JUN 1 4 2006 B

CofCA

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: A. Do
NORIBUMI KOITABASHI ET AL.)	
	:	Group Art Unit: 2853
Appln. No.: 09/931,256)	
	:	Patent No.: US 6,918,656 B2
Filed: August 17, 2001)	
•	:	Issued: July 19, 2005
For: INK-JET APPARATUS EMPLOYING)	• .
INK-JET HEAD HAVING A PLURALITY	:	June 14, 2006
OF INK EJECTION HEATERS)	•
CORRESPONDING TO EACH INK	:	Co
EJECTION OPENING)	of Correction
		ON , Sale
Commissioner for Patents		of C 3 2006
P.O. Box 1450		Correcti
Alexandria, VA 22313-1450		-C1/0/1

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the

Patent and Trademark Office due to errors which appear in the printed patent as a result of

Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor

character, which were not the fault of the Patent and Trademark Office. A Certificate of

Correction form (Form PTO-1050), in duplicate, is enclosed.

86/15/2006 SZEUDIE1 80000022 6918656

81 FC:1811

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Mark A. Williamson Attorney for Patentees

Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

MAW/llp

DC_MAIN 221110v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,918,656 B2

DATED

July 19, 2005

INVENTOR(S) :

Koitabashi et al.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE COVER PAGE

Item (56), References Cited, Foreign Patent Documents, "JP 61-46556 7/1986" should read -- JP 61-146556 7/1986--.

Item (57), Abstract, line 10, "printing," should read --printing--.

COLUMN 2

Line 13, "inkjet" should read --ink-jet--.

COLUMN 5

Line 28, "arranged" should read --having--.

Line 38, "arranged" should read --having--.

Line 47, "arranged" should read --having--.

COLUMN 6

Line 55, "-ejection" should read --ejection--.

COLUMN 8

Line 12, "- in" should read --in--.

COLUMN 9

Line 46, "a still" should read --still another--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone


Form PTO 1050 (Rev. 3-82)

(Form#30) MAW/IIp DC_MAIN 221111

(212) 218-2200 - Facsimile

PATENT NO. US 6,918,656 B2

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,918,656 B2

DATED

July 19, 2005

INVENTOR(S) :

Koitabashi et al.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10

Line 23, "stage 10a" should read --stage 110a--.

Line 24, "holder 10c" should read --holder 110c--.

Line 37, "be" should read --to--.

COLUMN 11

Line 62, "area" should read -- area.--.

COLUMN 12

Line 2, "election" should read --ejection--.

Line 27, "modes. (360" should read --modes.-- and --(360-- should start a new paragraph.

Line 28, "mode) This" should read --mode).-- and --This-- should start a new paragraph.

Line 33, "SH1. (720" should read --SH1.-- and --(720)--. should start a new paragraph.

Line 51, "embodiment" (first occurrence) should read --embodiment.--.

COLUMN 13

Line 4, "S9):" should read --S9).--.

Line 13, "in." should read --in--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies

PATENT NO. US 6,918,656 B2

@ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,918,656 B2

DATED

July 19, 2005

INVENTOR(S) :

Koitabashi et al.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 43, "sane." should read -- the same.--.

COLUMN 16

Line 6, " $\Delta T \ge -1$ °C" should read $--\Delta T \le -1$ °C--.

Line 8, "side,. the" should read --side, the--.

COLUMN 20

Line 1, "theaters" should read -- the heaters--.

COLUMN 23

Line 16, "having the in the case" should be deleted.

COLUMN 24

Line 54, "data" should read --data.--.

COLUMN 27

Line 45, "ink-Jet" should read --ink-jet--.

COLUMN 28

Line 31, "cycle" should read --cycles--.

COLUMN 29

Line 11, "are" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) MAW/Ip DC_MAIN 221111

PATENT NO. US 6,918,656 B2

No. of add'l. copies @ 30¢ per page

□> __

JUN 19 2006

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,918,656 B2

DATED

July 19, 2005

INVENTOR(S) :

Koitabashi et al.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30

Line 21, "to." should read --to--.

Line 64, "cycle" should read --cycle.--.

COLUMN 33

Line 41, "patents;" should read --patents.--.

Line 63, "commented" should read --connected--.

COLUMN 34

Line 67, "said method comprising the step of:" should read --said apparatus comprising:--.

COLUMN 35

Line 1, "selecting" should read --means for selecting--.

COLUMN 36

Line 34, "and" should be deleted.

Line 37, "all the" should read --all of the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) MAW/Ip DC_MAIN 221111

PATENT NO. US 6,918,656 B2

No. of add'l. copies @ 30¢ per page

➡ ___

JUN 15 ZOOR